



770-413-9126 · wscmotorsports.com · sales@wscmotorsports.com

January 2005
ONLINE CATALOG

Chevrolet Restoration Parts Catalog

Chevrolet - GMC
1973 - 77

Chevelle / Malibu / Laguna / Type S-3 / Monte Carlo
El Camino / GMC Sprint

1973 - 1974 - 1975 - 1976 - 1977
Chevrolet - GMC
Chevelle / Malibu / Laguna / Type S-3 / Monte Carlo
El Camino / GMC Sprint

2005 Catalog Rev. (0305)				
Picture	Part #	Application / Description	Ship By	Price
Headlamp Adjusting Hardware				
	4034-069-731S	1973-74 (except Laguna) Headlamp Adjuster Kit (10 pieces)	FedEx/UPS	\$ 9.95 kit
	HWB2107	1973-74 Screw, box of 50	FedEx/UPS	\$ 12.50 box
	HWB2104	1973-74 Nut, box of 50	FedEx/UPS	\$ 9.95 box
	HWB2108	1975-77 Screw and Nut, box of 25	FedEx/UPS	\$ 12.50 box
	HW2116	1973-77 Spring (with round headlamp) (except 1973-74 Laguna) (use 2)	FedEx/UPS	\$ 5.95 ea
	HWB2135	1973-74 Laguna Spring, box of 25	FedEx/UPS	\$ 12.50 box
	HWB2114	1976-77 (with 4 square headlamps) Spring, box of 25	FedEx/UPS	\$ 12.50 box
Fender Emblems				
	4033-130-711	1973 "Malibu" (use 2) (new GM)	FedEx/UPS	\$ 29.95 ea
Hood Pad Clips				
	HWB2401	1973-77, box of 25	FedEx/UPS	\$ 5.95 box
Hood Adjustment Bumpers				
	4012-205-73	1973-77 Hood Adjustment Rubber Bumper and Stud Assembly (use 2 per car)	FedEx/UPS	\$ 1.95 ea
	4010-205-641	1973-77 Hood Adjustment Nuts (use 2 per car)	FedEx/UPS	\$.95 ea
	4020-206-67P	1973-77 Hood / Fender Side Bumpers (use 2 pair per car)	FedEx/UPS	\$ 4.95 pr
Hood Hinge Springs				
	4011-211-66	1973-77 (use 2 per car)	FedEx/UPS	\$ 19.95 ea
Windshield Wiper Parts				
	4010-242-623	1973-77 Washer Reservoir Cap	FedEx/UPS	\$ 3.50 ea
Power Brake Booster Check Valve				
	4010-297-62	1973-77 Check Valve with Grommet	FedEx/UPS	\$ 8.95 ea
Battery Trays				
	4034-300-74	1973-77	FedEx/UPS	\$ 49.95 ea
Battery Tray Hardware				
	4031-301-66S	1973-77 Hold Down Bracket and Bolt Set	FedEx/UPS	\$ 4.95 set
Fan Shrouds				
	4033-310-711S	1973-77 small-block V8 (with A/C or HD Cooling)	FedEx/UPS	\$ 89.95 ea
	4033-310-712S	1973-75 big-block V8 (without A/C or HD Cooling) (upper and lower 2-piece set)	FedEx/UPS	\$ 119.95 set
	4033-310-713S	1973-75 big-block V8 (with A/C or HD Cooling) (upper and lower 2-piece set)	FedEx/UPS	\$ 119.95 set

Radiator Mount Cushions				
	4012-326-73	1973-77 with small-block Chevy V8 (use 4 per car) (used between radiator and core support)	FedEx/UPS	\$ 4.95 ea
	4021-326-72	1973-75 with big-block Chevy V8 (use 4 per car) (used between radiator and core support)	FedEx/UPS	\$ 4.95 ea
Firewall Plugs and Seals				
	4030-374-641S	1973-77 Heater Block-Off Plate Set (for models with heater delete)	FedEx/UPS	\$ 179.95 set
Heater Core / Blower Motor Case				
	4030-379-641	1973-77 (without A/C)	FedEx/UPS	\$ 49.95 ea
Door Hinge Repair Kits				
	4046-402-69S	1973-77 (set of bushings and pins for front hinges)	FedEx/UPS	\$ 14.95 set
	4012-402-68S	1973-77 Hinge Bolt Set	FedEx/UPS	\$ 19.95 set
Window Crank Handles				
	4013-421-77	1977 with clear knob <i>NOTE: Can use for 1973-76 but is incorrect.</i>	FedEx/UPS	\$ 4.95 ea
Outside Door Handles				
	4034-440-76L / R	1977 Door Handles LH / RH	FedEx/UPS	\$ 29.95 ea
	4021-440-702	1973-77 Door Handles Escutcheons (use 1 per handle)	FedEx/UPS	\$ 5.95 ea
Interior Trim Panel Parts				
	4010-453-621S	1973-77 Plastic Interior Trim Panel Mounting Plugs (set of 12) (use as required)	FedEx/UPS	\$ 9.95 set
	4010-453-622	1973-77 Metal Interior Trim Panel Mounting Clip (use as required)	FedEx/UPS	\$ 2.50 ea
	4021-453-701S	1973-77 Plastic Door Panel Mounting Clip (box of 50)	FedEx/UPS	\$ 11.95 box
Door Lock Knobs and Ferrules				
	4021-491-70	1973-77 Chrome Knob (use 2) (with smooth stem)	FedEx/UPS	\$ 2.95 ea
	4012-492-68	1973-76 Ferrule (use 2-4)	FedEx/UPS	\$ 2.95 ea
	4013-492-77	1977 Ferrule (use 2-4)	FedEx/UPS	\$ 2.95 ea
Dash Parts				
	4011-523-6710	1973-77 Heat or A/C Control Panel Knob (chrome) (use as required)	FedEx/UPS	\$ 3.50 ea
Dome / Courtesy Lamp Parts				
	4013-531-771	1977 (except El Camino / Sprint) Dome Lamp Lens (round)	FedEx/UPS	\$ 5.95 ea
	4013-531-772	1973-77 (except Convertible / El Camino / Sprint) Dome Lamp Housing (round)	FedEx/UPS	\$ 14.95 ea
	4320-531-693	1973-77 (except El Camino / Sprint) Dome Lamp Lens (with reading lamps)	FedEx/UPS	\$ 5.95 ea
	4082-531-681	1973-77 El Camino / Sprint Dome Lamp Lens	FedEx/UPS	\$ 4.95 ea
	4082-531-69	1973-77 El Camino / Sprint Dome Lamp Housing	FedEx/UPS	\$ 19.95 ea
Steering Wheel Parts				
	4030-542-641S	1973-77 Steering Wheel Horn Contact / Eyelet / Spring Set	FedEx/UPS	\$ 4.95 set

	4012-542-716	1973-77 Sport Steering Wheel Hub Retainer	FedEx/UPS	\$ 5.95 ea
	4012-542-717	1973-77 Sport Steering Wheel Horn Blowing Contact	FedEx/UPS	\$ 1.95 ea
Turn Signal / Tilt Wheel Lever Parts				
	4331-543-673	1973-77 Turn Signal Lever with Knob (Black) (paint to match other interior colors) (with cruise control)	FedEx/UPS	\$ 164.95 ea
	4012-543-713	1973-77 Column Shift Lever Knob (Black) (paint to match other interior colors)	FedEx/UPS	\$ 2.95 ea
Console Parts				
	4321-551-761	1973-77 A/T Slider Shift Seal	FedEx/UPS	\$ 7.50 ea
Console Shifter Parts				
	4320-551-694	1973-77 A/T Shifter Button Retaining Clip	FedEx/UPS	\$ 1.50 ea
	4320-551-695	1973-77 A/T Shifter Button Retaining Snap Ring	FedEx/UPS	\$.95 ea
Lug Nuts				
	4000-586-1S	1973-77 all, Box of 50, 7/16-20 (standard lug nuts)	FedEx/UPS	\$ 14.95 box
	4312-586-71	1973-77 14" x 7" Chevrolet Rally, correct design, stainless capped (7/16-20)	FedEx/UPS	\$ 1.95 ea
Wheel Center Caps				
	4012-588-681	1973-77 15" Rally Wheel Center Cap Assembly (use 4 per car)	FedEx/UPS	\$ 99.95 ea
	4012-588-682	1973-77 15" Rally Wheel Center Cap only (Chevrolet Motor Division) (use 4 per car)	FedEx/UPS	\$ 69.95 ea
	4011-588-672	1973-77 15" Rally Wheel Center Cap Base only (use 4 per car)	FedEx/UPS	\$ 24.95 ea
	4011-588-674S	1973-77 15" Rally Wheel Center Cap Screw Set (for mounting cap to base) (set of 5 screws)	FedEx/UPS	\$ 7.50 set
Front Disc Brake Backing Plates				
	4021-595-73L / R	1973-77 LH / RH	FedEx/UPS	\$ 19.95 ea
Quarter Panel Skins				
	4034-600-73L / R	1973-77 Chevelle 2-door, LH / RH, 30" high x 70" long (modify side marker hole and rear bumper for 1973 models)	Truck	\$ 169.95 ea
	4084-600-73L / R	1973-77 El Camino / Sprint, LH / RH, 30" high x 78" long	Truck	\$ 169.95 ea
	4061-600-76L / R	1976-77 Monte Carlo, LH / RH, 33" high x 69" long	Truck	\$ 169.95 ea
Door Jamb Striker Peg				
	4047-606-71	1973-76 (use 2-4) (collar included)	FedEx/UPS	\$ 39.95 ea
	4034-606-77	1977 (use 2-4) (collar included)	FedEx/UPS	\$ 39.95 ea
Rear Quarter Ashtrays				
	4012-647-70	1973-77 Wagon Ashtray Assembly (use 2 per car) (with "smooth" lid)	FedEx/UPS	\$ 24.95 ea
	4012-647-681P	1973-77 Wagon Rear Ashtray Inserts only (LH / RH pair)	FedEx/UPS	\$ 14.95 pr
Trunk Weatherstrips				
	4030-703-64	1973-77	FedEx/UPS	\$ 19.95 ea
Spare Tire / Jack Stowage Brackets				
	4021-726-701	1973-77 Spare Tire Hold-Down Bracket	FedEx/UPS	\$ 11.95 ea

	4011-726-671	1973-77 Spare Tire Wing Nut	FedEx/UPS	\$ 6.95 ea
	4021-726-75	1973-77 Spare Tire J-Bolt (5/16-18 x 6) (trim to original size)	FedEx/UPS	\$ 11.95 ea
Gas Tank Mounting Straps				
	4034-749-73P	1973-77 except wagon / El Camino / Sprint, LH / RH pair	FedEx/UPS	\$ 29.95 pr
Gas Tanks				
	4034-750-731	1973 w/ filler neck except wagons / El Camino	FedEx/UPS	\$ 169.95 ea
	4034-750-74	1974-77 w/ filler neck except wagons / El Camino	FedEx/UPS	\$ 169.95 ea
	4084-750-731	1973-77 El Camino / Sprint w/ filler neck	FedEx/UPS	\$ 249.95 ea
Gas Caps				
	4012-757-711	1973-74 all	FedEx/UPS	\$ 12.50 ea
	4013-757-75	1975-77 all	FedEx/UPS	\$ 9.95 ea
Tailgate Hardware				
	4082-825-683S	1973-77 El Camino / Sprint Tailgate Cable Kit (cables, bolts, and springs)	FedEx/UPS	\$ 39.95 kit
Gas Pedal Pads and Parts				
	4012-911-681	1973-77 Gas Pedal Pad	FedEx/UPS	\$ 6.95 ea
	4012-911-683	1973-77 Gas Pedal Pad Mounting Pin	FedEx/UPS	\$ 2.95 ea
	4034-911-731	1973-77 Gas Pedal Pad Tension Spring	FedEx/UPS	\$ 1.95 ea
M/T Clutch / Brake Pedal Pads and Trim				
	4047-912-711	1973-77 M/T Brake / Clutch Pedal Pad	FedEx/UPS	\$ 8.95 ea
	4047-912-712	1973-77 M/T Disc Brake Pedal Pad	FedEx/UPS	\$ 5.95 ea
Park Brake Pedal Pads and Trim				
	4020-914-671	1973-77 Park Brake Pedal Pad	FedEx/UPS	\$ 4.95 ea
Clutch / Brake Pedal Parts				
	4010-915-621	1973-77 Brake / Clutch Pedal Bushing (use as required)	FedEx/UPS	\$ 1.25 ea
Sunvisor Support Brackets and Hardware				
	4034-941-731	1973-77 Sunvisor Support (use 2 per car)	FedEx/UPS	\$ 59.95 ea
	4034-941-732	1973-77 Sunvisor Support Bushing (use 2 per car)	FedEx/UPS	\$ 1.95 ea
Clutch Linkage Parts				
	4041-951-587S	1973-77 Clutch Bellcrank Pivot Kit (nylon seals and springs)	FedEx/UPS	\$ 6.95 kit
	4041-951-589P	1973-77 Clutch Bellcrank Pivot Felt Seals (pair for one car)	FedEx/UPS	\$ 5.95 pr
	4010-951-652	1973-77 Bellcrank Engine Pivot Stud	FedEx/UPS	\$ 9.95 ea
	4046-951-694	1973-77 Bellcrank Frame Pivot Stud	FedEx/UPS	\$ 14.95 ea
	4030-951-6413	1973-77 Clutch Fork Boot	FedEx/UPS	\$ 9.95 ea

If you don't find the item you are looking for, give us a call at 770-413-9126 or send an [Email](#). New parts are always in the works.

Prices and availability are subject to change without notice.
Prices do not include shipping.

Shipping

Most smaller parts and shipments are shipped FedEx ground or UPS.

Parts marked as "Truck" are too large for FedEx or UPS and must be shipped by truck.

Most truck lines charge additional rates or surcharges for residential deliveries.

The best rates are to a business in a commercial zoned area or you pick up from the truck terminal.

Chevrolet, Pontiac, Oldsmobile, Buick, GMC, Chevy II, Nova, Camaro, Rally Sport, Z/28, "SS", Type LT, Berlinetta, Firebird, Esprit, Formula, Trans Am, 400, Chevelle, Malibu, SS-396, El Camino, Monte Carlo, Tempest, LeMans, GTO, Grand Prix, F-85, Cutlass, Cutlass Supreme, 4-4-2, Special, Skylark, GS, Biscayne, Bel Air, Impala, Caprice, S-10, S-15, Sonoma, Syclone, Typhoon, CST, Cheyenne, Suburban, Blazer, Jimmy, Tahoe, Yukon, Sprint, and Caballero are trademarks of General Motors Corporation.

All descriptions using trademarked names are for reference purposes only.

Copyright © WSC Motorsports 1991-2005 All Rights Reserved.
Revised Mar 15, 2005