



770-413-9126 · [wscmotorsports.com](http://wscmotorsports.com) · [sales@wscmotorsports.com](mailto:sales@wscmotorsports.com)

**January 2005**  
**ONLINE CATALOG**

**Oldsmobile Restoration Parts Catalog**

**Oldsmobile**  
**1973 - 77**

**Cutlass / 4-4-2 / Supreme / Salon**

**1973 - 1974 - 1975 - 1976 - 1977  
Olds  
Cutlass / 4-4-2 / Cutlass Supreme / Cutlass Salon**

Picture	Part #	Application / Description	Ship By	Price
<b>Headlamp Adjusting Hardware</b>				
	HW2165	1973-75 Screw (use 4 per car)	FedEx/UPS	\$ 1.95 ea
	HWB2163	1973-75 Spring, box of 10	FedEx/UPS	\$ 29.95 box
	HWB2117	1976-77 Screw and Nut, box of 25	FedEx/UPS	\$ 22.50 box
	HWB2166	1976-77 Spring, box of 25	FedEx/UPS	\$ 27.50 box
<b>Hood Pad Clips</b>				
	HWB2401	1973-77, box of 25	FedEx/UPS	\$ 5.95 box
<b>Hood Adjustment Bumpers</b>				
	4534-205-73	1973-77 Hood Adjustment Rubber Bumper and Stud Assembly (use 2 per car)	FedEx/UPS	\$ 1.95 ea
	4010-205-641	1973-77 Hood Adjustment Nuts (use 2 per car)	FedEx/UPS	\$ .95 ea
<b>Hood Hinge Springs</b>				
	4011-211-66	1973-77 Hood Hinge Spring (use 2 per car) (new GM part)	FedEx/UPS	\$ 19.95 ea
<b>Windshield Wiper Parts</b>				
	4010-242-623	1973-77 Washer Reservoir Cap	FedEx/UPS	\$ 3.50 ea
<b>Power Brake Booster Check Valve</b>				
	4010-297-62	1973-77 Check Valve with Grommet	FedEx/UPS	\$ 8.95 ea
<b>Battery Tray Hardware</b>				
	4031-301-66S	1973-77 Hold Down Bracket and Bolt Set	FedEx/UPS	\$ 4.95 set
<b>Firewall Plugs and Seals</b>				
	4030-374-641S	1973-77 Heater Block-Off Plate Set (for models with heater delete)	FedEx/UPS	\$ 179.95 set
<b>Heater Core / Blower Motor Case</b>				
	4030-379-641	1973-77 (without A/C)	FedEx/UPS	\$ 49.95 ea
<b>Door Hinge Repair Kits</b>				
	4046-402-69S	1973-77 (set of bushings and pins for front hinges)	FedEx/UPS	\$ 14.95 set
	4012-402-68S	1973-77 Hinge Bolt Set	FedEx/UPS	\$ 19.95 set
<b>Window Crank Handles</b>				
	4013-421-77	1977 with clear knob <i>NOTE: Can use for 1973-76 but is not correct.</i>	FedEx/UPS	\$ 4.95 ea
<b>Outside Door Handles</b>				
	4034-440-76L / R	1976-77 Door Handles LH / RH	FedEx/UPS	\$ 29.95 ea
	4021-440-702	1973-77 Door Handles Escutcheons (use 1 per handle)	FedEx/UPS	\$ 5.95 ea
<b>Interior Trim Panel Parts</b>				
	4010-453-621S	1973-77 Plastic Interior Trim Panel Mounting Plugs (set of 12) (use as required)	FedEx/UPS	\$ 9.95 set

	4010-453-622	1973-77 Metal Interior Trim Panel Mounting Clip (use as required)	FedEx/UPS	\$ 2.50 ea
	4021-453-701S	1973-77 Plastic Door Panel Mounting Clip (box of 50)	FedEx/UPS	\$ 11.95 box
<b>Door Lock Knobs and Ferrules</b>				
	4021-491-70	1973-77 Chrome Knob (use 2) (with smooth stem)	FedEx/UPS	\$ 2.95 ea
	4012-492-68	1973-76 Ferrule (use 2-4)	FedEx/UPS	\$ 2.95 ea
	4013-492-77	1977 Ferrule (use 2-4)	FedEx/UPS	\$ 2.95 ea
<b>Dash Parts</b>				
	4011-523-6710	1973-77 Heat or A/C Control Panel Knob (chrome) (use as required)	FedEx/UPS	\$ 3.50 ea
<b>Dome / Courtesy Lamp Parts</b>				
	4013-531-771	1977 Dome Lamp Lens (round)	FedEx/UPS	\$ 5.95 ea
	4013-531-772	1973-77 Dome Lamp Housing (round)	FedEx/UPS	\$ 14.95 ea
	4320-531-693	1973-77 Dome Lamp Lens (with reading lamps)	FedEx/UPS	\$ 5.95 ea
<b>Lug Nuts</b>				
	4000-586-1S	1973-77 all, Box of 50, 7/16-20 (standard lug nuts)	FedEx/UPS	\$ 14.95 box
	4312-586-71	1973-77 Super Stock II / III Wheel, 7/16-20, Stainless Capped.	FedEx/UPS	\$ 1.95 ea
<b>Wheel Trim Rings</b>				
	4320-587-692S	1973-77 14" x 7" Rally Wheel Trim Ring (set of 4)	FedEx/UPS	\$ 99.95 set
	4346-587-69	1973-77 15" x 7" Rally Wheel Trim Ring (use 4) (new GM)	FedEx/UPS	\$ 99.95 ea
<b>Wheel Center Caps</b>				
	4532-588-681	1973-74 Super Stock II / III Center Cap (use 4) (new GM)	FedEx/UPS	\$ 69.95 ea
	4532-588-682	1973-74 Super Stock II / III Center Cap Screws (use 5 per wheel) (new GM)	FedEx/UPS	\$ 1.25 ea
	4534-588-751	1975-77 Super Stock II / III Center Cap (use 4) (new GM)	FedEx/UPS	\$ 94.95 ea
	4534-588-752	1975-77 Super Stock II / III Center Cap Retainer (use 4) (new GM)	FedEx/UPS	\$ 4.95 ea
<b>Front Disc Brake Backing Plates</b>				
	4021-595-73L / R	1973-77 LH / RH	FedEx/UPS	\$ 19.95 ea
<b>Quarter Panel Skins</b>				
	4534-600-76L / R	1976-77 2-door, LH / RH, 30" high x 65" long	Truck	\$ 169.95 ea
<b>Door Jamb Striker Peg</b>				
	4047-606-71	1973-76 (use 2-4) (collar included)	FedEx/UPS	\$ 39.95 ea
	4034-606-77	1977 (use 2-4) (collar included)	FedEx/UPS	\$ 39.95 ea
<b>Rear Quarter Ashtrays</b>				
	4012-647-70	1973-77 Wagon Ashtray Assembly (use 2 per car) (with "smooth" lid)	FedEx/UPS	\$ 24.95 ea
	4012-647-681P	1973-77 Wagon Rear Ashtray Inserts only (LH / RH pair)	FedEx/UPS	\$ 14.95 pr
<b>Trunk Weatherstrips</b>				
	4030-703-64	1973-77	FedEx/UPS	\$ 19.95 ea

<b>Spare Tire / Jack Stowage Brackets</b>				
	4021-726-701	1973-77 Spare Tire Hold-Down Bracket	FedEx/UPS	\$ 11.95 ea
	4011-726-671	1973-77 Spare Tire Wing Nut	FedEx/UPS	\$ 6.95 ea
	4021-726-75	1973-77 Spare Tire J-Bolt (5/16-18 x 6) (trim to original size)	FedEx/UPS	\$ 11.95 ea
<b>Gas Tank Mounting Straps</b>				
	4034-749-73P	1973-77 except Wagon, LH / RH pair	FedEx/UPS	\$ 29.95 pr
<b>Gas Tanks</b>				
	4034-750-731	1973 w/ filler neck except Wagons	FedEx/UPS	\$ 169.95 ea
	4434-750-73	1974-75, 1976-77 4-door w/ filler neck except Wagons	FedEx/UPS	\$ 169.95 ea
	4034-750-74	1976-77 2-door w/ filler neck	FedEx/UPS	\$ 169.95 ea
<b>Gas Caps</b>				
	4012-757-711	1973-74 all	FedEx/UPS	\$ 12.50 ea
	4013-757-75	1975-77 all	FedEx/UPS	\$ 9.95 ea
<b>Gas Pedal Pads and Parts</b>				
	4532-911-68	1973-77 Gas Pedal Pad	FedEx/UPS	\$ 17.50 ea
<b>M/T Clutch / Brake Pedal Pads and Trim</b>				
	4047-912-711	1973-77 Clutch / Brake Pedal Pad (use 1-2 per car) (except Disc Brake Pad)	FedEx/UPS	\$ 8.95 ea
	4047-912-712	1973-77 Disc Brake Pedal Pad	FedEx/UPS	\$ 5.95 ea
<b>Park Brake Pedal Pads and Trim</b>				
	4020-914-671	1973-77 Park Brake Pedal Pad	FedEx/UPS	\$ 4.95 ea
<b>Clutch / Brake Pedal Parts</b>				
	4010-915-621	1973-77 Brake / Clutch Pedal Bushing (use as required)	FedEx/UPS	\$ 1.25 ea
<b>Sunvisor Support Brackets and Hardware</b>				
	4034-941-731	1973-77 Sunvisor Support (use 2 per car)	FedEx/UPS	\$ 59.95 ea
	4034-941-732	1973-77 Sunvisor Support Bushing (use 2 per car)	FedEx/UPS	\$ 1.95 ea
<b>Clutch Linkage Parts</b>				
	4041-951-587S	1973-77 Clutch Bellcrank Pivot Kit (nylon seals and springs)	FedEx/UPS	\$ 6.95 kit
	4041-951-589P	1973-77 Clutch Bellcrank Pivot Felt Seals (pair for one car)	FedEx/UPS	\$ 5.95 pr
	4030-951-6413	1973-77 Clutch Fork Boot	FedEx/UPS	\$ 9.95 ea

**If you don't find the item you are looking for, give us a call at 770-413-9126 or send an [Email](#). New parts are always in the works.**

**Prices and availability are subject to change without notice.  
Prices do not include shipping.**

### **Shipping**

**Most smaller parts and shipments are shipped FedEx ground or UPS.**

**Parts marked as "Truck" are too large for FedEx or UPS and must be shipped by truck.**

**Most truck lines charge additional rates or surcharges for residential deliveries.**

**The best rates are to a business in a commercial zoned area or you pick up from the truck terminal.**

Chevrolet, Pontiac, Oldsmobile, Buick, GMC, Chevy II, Nova, Camaro, Rally Sport, Z/28, "SS", Type LT, Berlinetta, Firebird, Esprit, Formula, Trans Am, 400, Chevelle, Malibu, SS-396, El Camino, Monte Carlo, Tempest, LeMans, GTO, Grand Prix, F-85, Cutlass, Cutlass Supreme, 4-4-2, Special, Skylark, GS, Biscayne, Bel Air, Impala, Caprice, S-10, S-15, Sonoma, Syclone, Typhoon, CST, Cheyenne, Suburban, Blazer, Jimmy, Tahoe, Yukon, Sprint, and Caballero are trademarks of General Motors Corporation.

All descriptions using trademarked names are for reference purposes only.

Copyright © WSC Motorsports 1991-2005 All Rights Reserved.

Revised Feb. 17, 2005